


Note: Must be tacked up before welding and placed flat on table, No flipping project when welding
 All groove welds full penetration .

DRAWN Scott Friesen 	28/01/2014	2023 Regional - Steps		

